

Error Memory

Date: 3.1.2022 17:11:18

VIN: WBAVU51000A301736

00 Safety and information module (SIM)

2 errors

A6CF: AUC SENSOR

9C69: FONDSCHICHTUNGSPOTENTIOMETER

12 Motor electronics

1 error

4390: 4390 Charge air temperature sensor, signal