

CARLY DIAGNOSTICS REPORT

BMW



16.9.2023

OVERVIEW

Status

BAD

Issues

74

Systems

Overall Carly identified **27 control units** in your Car.

Summary

Your car has **1 critical issues** inside of **1** different systems. Our mechanics recommend to check these issues first.



— Critical control units
— Severe control units
— Moderate control units

SYSTEMS WITH ISSUES

Engine

258400

Exhaust temperature sensor upstream of the oxidation catalytic converter, signal: too high

Severe

Last occurred at:
205923 km

258400

Exhaust temperature sensor upstream of the oxidation catalytic converter, signal: too high

Severe

Last occurred at:
202795 km

2AD200

Check Control message (ID 229):
Charging battery

Moderate

Last occurred at:
198363 km

INFO 289800

Engine process variables: deviation too high

Last occurred at:
196497 km

INFO 254C00

Info - security case: accelerator and brake simultaneously active

Last occurred at:
197374 km

INFO 341C00

EGR cooling, plausibility: temperature after cooler in the bypass operation to high

Last occurred at:
197311 km

INFO 27AB00

DDE control unit internal (cyclic authentication): record check is not okay

Last occurred at:
196497 km

Dynamic Stability Control (DSC)

480AB5

Transfer box: Temporary fault, protective function

Severe

Air Conditioning

8011F9

Electric auxiliary heater (low voltage):
Reduced heating output by power management

Moderate

Last occurred at:
196499 km

INFO 07802B

Comm e net start ind channel 0

INFO 078022

Message (vehicle condition 0×3a0) is missing

Last occurred at:
205761 km

INFO 078043

Linif e response

030410 Multifunction steering wheel (MFL):
Missing LIN slave

Severe

Last occurred at:
202880 km

D90C0D LIN master K_LIN_11: No
communication

Moderate

Last occurred at:
202880 km

INFO 804029 Sek battery undervoltage

Last occurred at:
196554 km

INFO 93071F Buffer for outgoing error messages is full

Last occurred at:
196511 km

8041A8 Welcome light repeat lock active

Moderate

Last occurred at:
204485 km

INFO 101715

Positioning not possible over 10 minutes

Last occurred at:
200269 km

E59418

Signal (vehicle condition, 0×3A0)
invalid, transmitter FEM

Moderate

Last occurred at:
200697 km

INFO 8032B5

Ultrasonic sensor, rear outer left: acoustic
or electromagnetic interference

Last occurred at:
198362 km

INFO 8032BD

Rear ultrasonic sensor center left: acoustic
or electromagnetic interference

Last occurred at:
198362 km

INFO 8032C5

Ultrasonic sensor, rear center right:
acoustic or electromagnetic interference

Last occurred at:
198362 km

INFO 8032CD

Ultrasonic sensor, rear right outside:
acoustic or electromagnetic interference

Last occurred at:
198362 km

INFO 8032D5

Ultrasonic sensor, front left outside:
acoustic or electromagnetic interference

Last occurred at:
198362 km

INFO 8032DD

Ultrasonic sensor, front center left:
acoustic or electromagnetic interference

Last occurred at:
198362 km

INFO 8032E5

Ultrasonic sensor, front center right:
acoustic or electromagnetic interference

Last occurred at:
198362 km

INFO 8032ED

Ultrasonic sensor front outer right:
acoustic or electromagnetic interference

Last occurred at:
198362 km

INFO 8049E5

Cnm e network timeout

Last occurred at:
200532 km

INFO 420010

Stepper motor driver headlamp leveling:
cold warning (warning)

Last occurred at:
196798 km

INFO 420011

Stepper motor driver headlights: cold
warning (warning)

Last occurred at:
196798 km

INFO 420012

Stepper motor driver glare-free high
beam: cold warning (warning)

Last occurred at:
196753 km

INFO 420006

Reset

INFO 420300

Signal (relative timing counter, 0×328):
void

Last occurred at:
196499 km

Instrument Cluster

INFO E12C2F

Hu interface (acknowledgment requirement combination, 0×172): signal faulty

Last occurred at:
196497 km

Central Gateway

CD0487

ZGM: Synchronisation process for FlexRay failed

Moderate

Last occurred at:
200697 km

INFO 100600

Flexray protocol startup time is too high

Last occurred at:
196497 km

INFO 100100

Lost contact with fcm slave

Last occurred at:
198909 km

INFO 100203

Dm software error info warning

Last occurred at:
196497 km

INFO 100204

Botschafts monitoring: failed system
context signal

Last occurred at:
196497 km

INFO 100300

Commissioning could not be performed
because tas already busy

Last occurred at:
198150 km

INFO 100001

Vcmresultsvtcheck - identity check: there
are differences between the svt and is
recognized svt target.

Last occurred at:
200269 km

INFO 100601

Unexpected asynchronous state
flexraybus

Last occurred at:
198909 km

INFO 101008

Not resolvable ambiguous routing - sg is
not in the target table svt

INFO 100104

HW weckgrund zgw

Fuel Pump

Transmission

INFO 440011

Message (vehicle condition 0×3a0) is missing, transmitter zgw

Last occurred at:
196532 km

Speech Recognition

Anti Theft Alarm System

INFO 410010

Stepper motor driver headlamp leveling: cold warning (warning)

Last occurred at:
196798 km

INFO 410011

Stepper motor driver headlights: cold warning (warning)

Last occurred at:
196753 km

INFO 410012

Stepper motor driver glare-free high beam: cold warning (warning)

Last occurred at:
196798 km

INFO 410006

Reset

INFO 410300

Signal (relative timing counter, 0×328):
void

Last occurred at:
196499 km

Electr. Ride Height Control

Seat Belt Tensioner Right

ABS & Stability Control

INFO 030222

Shd: automatic initialization

Last occurred at:
201587 km

INFO 801A20

Can e timeout

Last occurred at:
202222 km

Gear Lever

High Beam

INFO 5F0000

Information storage: complete online
calibration initial

Last occurred at:
196497 km

Telematics

INFO 610019

Nvm e integrity failed

INFO E14426

Invalid signal in CAN message gps po exts most

Last occurred at:
196497 km

INFO E1442C

Invalid signal in CAN message stat zv klappen

Last occurred at:
196497 km

INFO E14437

Invalid signal in CAN message gps po most

Last occurred at:
196652 km

INFO E14413

Timeout CAN message stat gang backwards

Last occurred at:
196497 km

INFO E14405

Timeout CAN message mile veh

Last occurred at:
198049 km

INFO E14406

Timeout CAN message gps po exts most

Last occurred at:
196497 km

INFO E14411

Timeout CAN message v veh

Last occurred at:
198909 km

INFO E14414

Timeout CAN message stat zv klappen

Last occurred at:
196497 km

Central Control Unit

Rear Seat (driver side)

Trailer Hitch

802832

Fully automatic trailer tow hitch:
Intermediate setting detected

Last occurred at:
198363 km

Severe