

Error Memory

Date: 3.1.2022 16.52.44

VIN: WBAVU51000A301736

00 Safety and information module (SIM)

3 errors

A6CF: AUC SENSOR

9C69: FONDSCHICHTUNGSPOTENTIOMETER

A6D1: ADDITIONAL WATER PUMP

01 Safety and information module

1 error

93FB: SBR function - speed signal missing

12 Motor electronics

15 errors

4391: 4391 Charge air temperature sensor, signal

4390: 4390 Charge air temperature sensor, signal

4CA0: 4CA0 oil pressure switch, plausibility

480A: 480A particulate filter system

4C2F: 4C2F DDE controller internal (MonLimSet)

4C2E: 4C2E DDE controller internal (MonLimLead)

4C29: 4C29 DDE controller internal (MonLimCurr)

4C03: 4C03 message (OPERATION_TEMPOMAT, 0x194)

4992: 4992 message (STAT_KOMBI, 0x1B4)

3F62: 3F62 Vehicle speed signal via CAN

41F2: 41F2 electric fan, control

4BDA: 4BDA Fuel Pre-Feed Pressure Control (Layer_NDR1)

4590: 4590 Rail pressure plausibility volume controlled

4BF3: 4BF3 message (WAERMESTROM_KLIMA, 0x1B5)

49B8: 49B8 message (STAT_EKP, 0x335)

30 Electromechanical power steering

2 errors

D515: Message from the PT-CAN (steering wheel angle above, ID = 0c4h) (FC 06)

D517: Message from the PT-CAN (speed, ID = 1a0h) (FC 09)

40 Car access system

1 error

A0B5: Signalerkennung_Geschwindigkeit_Fehler

56 Roof function centre

1 error

A66E: Error interior light rear 0xA66E

60 Instrument panel

4 errors

A3AC: CAN_ID_1A6_ERROR_Ausfall_Botschaft_Wegstrecke

A550: ID_Ausfall 1A0h speed

A3B9: CAN_ID_19E_ERROR_Ausfall_Botschaft_Status_DSC

A54D: ID_Failure or Alive EKP

63 Headunit/radio

2 errors

ABD4: 0xABD4: RAD ON open circuit error

E1D1: 0xE1D1: DSC transmitter failure

72 Basic body module

4 errors

E597: Telegram Status DSC Timeout

E599: Telegram speed timeout

E594: Telegram steering angle timeout

A8AC: Limiting light left defective

78 Heating/air-conditioning control

1 error

9C52: Ventilation flap (LIN)