

**BMW 5 series (2015)**

marrask. 12 2020

STATUS

**Bad**

TOTAL ISSUES

**3**

HEALTHY SYSTEMS

**44****Issues (2)****Engine**

Fault code: 280F00

The nox sensor according denox catalytic converter, signal nox: nox signal too long invalid

**Telematics**

Fault code: INFO E14413 Timeout CAN message stat gang backwards

Fault code: INFO E14414 Timeout CAN message stat zv klappen

## Healthy Systems (44)

---

✓ Central Gateway

---

✓ Cruise Control

---

✓ Passenger Seat

---

✓ TV Tuner

---

✓ Damper Rear Right

---

✓ Front Light Left

---

✓ Selective Catalytic Reduction

---

✓ Dynamic Stability Control (DSC)

---

✓ Immobilizer

---

✓ Damper Front Left

---

✓ Air Conditioning

---

✓ Integr. Chassis Module

---

✓ Tire Pressure Control

---

✓ Park Distance Control (PDC)

---

✔ Vertical Dynamic Management

---

✔ Car Access System

---

✔ Head-Up Display

---

✔ Electronic Parking Brake

---

✔ Tailgate

---

✔ Central Control Unit

---

✔ Roof Control Panel

---

✔ Speech Recognition

---

✔ Anti Theft Alarm System

---

✔ Steering Column Switch Cluster

---

✔ Transmission

---

✔ Gear Lever

---

✔ Driver Assistant

---

✔ Satellite Module Center

---

✔ Damper Rear Left

---

✓ Damper Front Right

---

✓ Rear Seat (driver side)

---

✓ Instrument Cluster

---

✓ Night Vision

---

✓ HiFi Amplifier

---

✓ Fuel Pump

---

✓ Junction Box Module

---

✓ Foot Well Module

---

✓ Lane Change Warning

---

✓ Radio

---

✓ Airbag

---

✓ Top Rear Sideview Camera

---