

Date: 10/05/17 20:15:41
 ECU: DDE40KW0
 JobStatus: OKAY
 Variant: DDE40KW0

 RESULT: 6 errors in error memory !

2550 Rail pressure control at start

Error frequency : 154
 Logistic counter: 38

Error occured 1. times at:

Engine speed	224.78	1/min
fuel pre-supply pressure	1.12	bar
Einspritzmenge	25.09	mm^3
RPC rail pressure	108.43	bar
Fehler aufgetreten bei	463360.00	km

Error occured 2. times at:

Engine speed	274.73	1/min
fuel pre-supply pressure	1.01	bar
Einspritzmenge	25.60	mm^3
RPC rail pressure	6.02	bar
Fehler aufgetreten bei	473970.00	km

Error occured 3. times at:

Engine speed	249.75	1/min
fuel pre-supply pressure	1.01	bar
Einspritzmenge	31.75	mm^3
RPC rail pressure	0.00	bar
Fehler aufgetreten bei	473970.00	km

Error not present
 Sporadic error
 Rail-pressure build up

Errorcode: 09 F6 26 9A F8 10 09 46 31 12 B5 00 10 0B 3F 32
 01 B9 25 10 0A 3F 3E 00 B9

13573 glow device

Error frequency : 188
 Logistic counter: 40

Error occured 1. times at:

Engine speed	849.15	1/min
Coolant temperature	17.68	Grad C
Einspritzmenge	10.24	mm^3
RPC rail pressure	373.49	bar
Fehler aufgetreten bei	463370.00	km

Error occured 2. times at:

Engine speed	874.13	1/min
Coolant temperature	10.18	Grad C
Einspritzmenge	8.19	mm^3
RPC rail pressure	0.00	bar
Fehler aufgetreten bei	473970.00	km

Error occured 3. times at:

Engine speed	0.00	1/min
Coolant temperature	15.64	Grad C
Einspritzmenge	22.53	mm^3
RPC rail pressure	0.00	bar
Fehler aufgetreten bei	473970.00	km

Error present
 Sporadic error
 Glow system - Glow-plug or Glow-plug relay

Errorcode: 35 05 28 BC FC 80 22 56 14 3E B5 01 80 23 4B 10
 00 B9 25 80 00 53 2C 00 B9

4704 Pre-supply pressure monitoring

Error frequency : 26
Logistic counter: 40

Error occurred 1. times at:

Engine speed	0.00	1/min
Air-temperature	61.38	Grad C
Einspritzmenge	23.55	mm^3
fuel pre-supply pressure	1.17	bar
Fehler aufgetreten bei	463390.00	km

Error occurred 2. times at:

Engine speed	424.58	1/min
Air-temperature	9.49	Grad C
Einspritzmenge	32.77	mm^3
fuel pre-supply pressure	0.99	bar
Fehler aufgetreten bei	473970.00	km

Error occurred 3. times at:

Engine speed	424.58	1/min
Air-temperature	9.49	Grad C
Einspritzmenge	32.77	mm^3
fuel pre-supply pressure	0.99	bar
Fehler aufgetreten bei	473970.00	km

Error present
Sporadic error
Pre-supply press.below min.value for eng.start

Errorcode: 12 60 28 1A FC 04 00 96 2E 49 B5 03 04 11 4A 40
3E B9 25 04 11 4A 40 3E B9

1152 Electric fan

Error frequency : 21
Logistic counter: 39

Error occurred 1. times at:

Engine speed	0.00	1/min
Coolant temperature	92.10	Grad C
Supply voltage	9.84	V
duty factor	4.73	%
Fehler aufgetreten bei	463390.00	km

Error occurred 2. times at:

Engine speed	0.00	1/min
Coolant temperature	12.22	Grad C
Supply voltage	12.27	V
duty factor	4.73	%
Fehler aufgetreten bei	473970.00	km

Error occurred 3. times at:

Engine speed	0.00	1/min
Coolant temperature	9.49	Grad C
Supply voltage	12.04	V
duty factor	4.73	%
Fehler aufgetreten bei	473970.00	km

Error not present
Sporadic error
Controll circuit or short circuit to positive B-

Errorcode: 04 80 27 15 F8 08 00 C3 55 0C B5 03 08 00 4E 6A
0C B9 25 08 00 4A 68 0C B9

4496 Rail-pressure plausibility

Error frequency : 3
Logistic counter: 40

Error occurred 1. times at:

Engine speed	2772.23	1/min
--------------	---------	-------

fuel pre-supply pressure	2.21	bar
Einspritzmenge	41.47	mm^3
RPC rail pressure	578.31	bar
Fehler aufgetreten bei	463740.00	km

Error occured 2. times at:

Engine speed	799.20	1/min
fuel pre-supply pressure	1.04	bar
Einspritzmenge	7.17	mm^3
RPC rail pressure	0.00	bar
Fehler aufgetreten bei	473970.00	km

Error occured 3. times at:

Engine speed	799.20	1/min
fuel pre-supply pressure	1.04	bar
Einspritzmenge	7.17	mm^3
RPC rail pressure	0.00	bar
Fehler aufgetreten bei	473970.00	km

Error present
Sporadic error
Control deviation over engine speed too great

Errorcode: 11 90 28 03 FC 20 6F 8A 51 60 B5 26 20 20 41 0E
00 B9 25 20 20 41 0E 00 B9

13589 air condition output

Error frequency : 2
Logistic counter: 34

Error occured 1. times at:

Engine speed	0.00	1/min
Coolant temperature	21.78	Grad C
Einspritzmenge	27.65	mm^3
RPC rail pressure	0.00	bar
Fehler aufgetreten bei	473970.00	km

Error occured 2. times at:

Engine speed	0.00	1/min
Coolant temperature	23.15	Grad C
Einspritzmenge	27.14	mm^3
RPC rail pressure	0.00	bar
Fehler aufgetreten bei	473970.00	km

Error not present
Sporadic error
Open circuit or short circuit to B-

Errorcode: 35 15 22 02 78 08 00 5C 36 00 B9 25 08 00 5E 35
00 B9 25 00 00 00 00 00 00

=====