

ISTA system version: 4.29.30.23425 Data version: R4.29.30 Programming data: 4.29.31

VIN: WBA5E7102GG567811 Vehicle: 5/F10/SEDAN/ - /B47,-/ AUTO/ECE/LL/2016/07

Int.lev.works: F010-16-07-505 Int.lev.(cur.): F010-17-03-505 Int.lev.(tar.): -

Mileage: -

Code	Description	Mileage	Existent	Class
C95403	No message (LCD brightness control, 0x393), ACSM receiver, instrument panel transmitter	0	yes	Information
CBD40A	No message (outside temperature, 0x2CA), receiver SCR, transmitter KOMBI	0	yes	Information
CBD40B	No message (relative time BN2020, 0x328), receiver SCR, transmitter KOMBI	0	yes	Information
CBD420	No message (kilometre reading, 0x330), receiver SCR, transmitter KOMBI	0	yes	Information
2BC600	Nitrogen oxide sensor upstream of SCR catalytic converter, message: Missing	328279	yes	
2BC300	Nitrogen oxide sensor upstream of SCR catalytic converter, message: Missing	328279	yes	
CD9403	No message (ambient temperature, 0x2CA), receiver DDE, transmitter KOMBI	328279	yes	Information
CD9438	No message (relative time, 0x328), receiver DDE, transmitter KOMBI	328279	yes	Information
CD9541	Message (units BN2020, 252.0.4) missing, receiver DDE, transmitter KOMBI	328279	yes	Information
CD9434	No message (kilometre reading/range, 0x330), receiver DDE, transmitter KOMBI	328279	yes	Information
CD94DE	No message (OBD sensor diagnosis status, 0x580-0x5FF), receiver DDE	328279	yes	Information
CD947B	No message (time/date, 0x2F8), receiver DDE, transmitter KOMBI	328279	yes	Information
CF19C1	Message (effect while driving: none) missing, EGS receiver, instrument cluster transmitter	-1	yes	Information
CF5408	No message (kilometre reading, 276.4.8), receiver VTG, transmitter KOMBI	328279	yes	Information
CF5488	Interface INSTR. CL. (kilometre reading, 276.4.8): signal invalid	328279	No	Information
D01428	Message (ambient temperature, 252.1.4) missing, receiver ICM, transmitter instrument panel	0	yes	Information
D014F2	Message (kilometre reading/range, 276.4.8) missing, receiver ICM, transmitter instrument panel	0	yes	Information
D0158C	Message (relative time, 276.2.8) missing, receiver ICM, transmitter instrument panel	0	yes	Information
D016DC	Message (status display of driving dynamics, 97.1.2) missing, receiver ICM, Transmitter instrument panel	0	yes	Information
D018B5	Message (status display, instrument panel, 97.0.2) missing, receiver ICM, transmitter, instrument panel	0	yes	Information
D01932	Message (time/date, 276.6.8) missing, receiver ICM, transmitter instrument panel	0	yes	Information

D35428	No message (ambient temperature, 252.1.4), receiver DSC, transmitter KOMBI	328279	yes	Information
D354F2	No message (kilometre reading/range, 276.4.8), receiver DSC, transmitter KOMBI	328279	yes	Information
D3558C	No message (relative time BN2020, 276.2.8), receiver DSC, transmitter KOMBI	328279	yes	Information
D514F2	No message (kilometre reading/range, 276.4.8), receiver EPS, transmitter KOMBI	-1	yes	Information
D5158C	No message (relative time, 276.2.8), receiver EPS, transmitter KOMBI	-1	yes	Information
E0940C	No message (LCD brightness control PT-CAN, 0x393), receiver GWS, transmitter KOMBI	-1	yes	Information
S 0386	No communication possible with: Instrument panel	-1	yes	
S 0275	Media Oriented System Transport ring break	-1	yes	
E21403	No message (outside temperature, 0x2CA), receiver PDC, transmitter KOMBI	-1	yes	Information
E71400	No message (ambient temperature, 0x2CA), receiver IHKA, transmitter KOMBI	-1	yes	Information
E71405	No message (liquid crystal display brightness control, 0x328), receiver IHKA, transmitter KOMBI	-1	yes	Information
E75400	No message (ambient temperature, 0x2CA), receiver FKA, transmitter KOMBI	-1	yes	Information
E75406	Message (LCD brightness control, 0x393) missing, receiver FKA, transmitter instrument cluster	-1	yes	Information