

---

ISTA system version: **4.10.15.15600**    Data version: **R4.10.15**    Programming data: -  
 VIN: **WBA5J31030D715489**    Vehicle: **5/F11/Sports Wagon/520d/N47/AUTO/ECE/LL/2014/03**  
 Int.lev.works: **F010-14-03-503**    Int.lev.(cur.): **F010-14-03-503**    Int.lev.(tar.): -  
 Mileage: **242419 km**

---

Code	Description	Mileage	Existent	Class
S 0380	No communication possible with: Crash safety module	242419	yes	
277C00	Message EWS-DDE incorrect Timeout EWS4 message	242419	yes	Information
CD840A	DDE, PT-CAN : Communications fault	242419	yes	
CD9541	Message (units BN2020, 252.0.4) missing, receiver DDE, transmitter KOMBI	242419	yes	Information
S 0237	No communication possible with: EKPS	242419	yes	
S 0235	No communication possible with: Electronic transmission control	242419	yes	
D01428	Message (ambient temperature, 252.1.4) missing, receiver ICM, transmitter instrument panel	0	yes	Information
D014F2	Message (kilometre reading/range, 276.4.8) missing, receiver ICM, transmitter instrument panel	0	yes	Information
D0158C	Message (relative time, 276.2.8) missing, receiver ICM, transmitter instrument panel	0	yes	Information
D01B00	Message (request, hydraulic function, 100.1.2) missing, receiver ICM, transmitter parking brake	0	yes	Information
D016DC	Message (status display of driving dynamics, 97.1.2) missing, receiver ICM, Transmitter instrument panel	0	yes	Information
D018B5	Message (status display, instrument panel, 97.0.2) missing, receiver ICM, transmitter, instrument panel	0	yes	Information
D01932	Message (time/date, 276.6.8) missing, receiver ICM, transmitter instrument panel	0	yes	Information
D35428	No message (ambient temperature, 252.1.4), receiver DSC, transmitter KOMBI	242419	yes	Information
D354F2	No message (kilometre reading/range, 276.4.8), receiver DSC, transmitter KOMBI	242419	yes	Information
D3558C	No message (relative time BN2020, 276.2.8), receiver DSC, transmitter KOMBI	242419	yes	Information
D356F5	No message (status, seat belt, contact, seat occupancy, 275.6.8), receiver DSC, transmitter ACSM	242419	yes	Information
D35B00	No message (request, hydraulic function, 100.1.2), receiver DSC, transmitter EMF	242419	yes	Information
S 0367	No communication possible with: Parking brake	242419	yes	
D514F2	No message (kilometre reading/range, 276.4.8), receiver EPS, transmitter KOMBI	-1	yes	Information
D5158C	No message (relative time, 276.2.8), receiver EPS, transmitter KOMBI	-1	yes	Information
D70DA2	No message (engine signal), receiver EHC, transmitter DME/DDE	0	yes	Information
D91410	Message (drive train 2 data, 230.0.2) incorrect, receiver CAS, transmitter DME / DDE	242419	yes	Information
S 0379	No communication possible with: Gear selector switch	242419	yes	

E0D400	No message (outside temperature, 0x2ca), receiver FLA, transmitter KOMBI	-1	yes	Information
E0D402	Message missing (drive train data 2, 0x3F9), FLA receiver, DME/DDE transmitter	-1	yes	Information
E0D408	Message missing (kilometre reading range, 0x330), FLA receiver, instrument panel transmitter	-1	yes	Information
E0D40C	Message missing (relative time, 0x328), FLA receiver, instrument panel transmitter	-1	yes	Information
E0D40E	No message (status, reverse gear, 0x3B0), receiver FLA, transmitter BDC/FEM/FRM	-1	yes	Information
E21403	No message (outside temperature, 0x2CA), receiver PDC, transmitter KOMBI	-1	yes	Information
E21407	No message (data drive train 2, 0x3F9), receiver PDC, transmitter DME/DDE	-1	yes	Information
E58510	Message (data, drive train 2, 0x3F9) missing, receiver FRM, transmitter DME/DDE	242419	yes	
E58511	Message (power management, 0x3B3) missing, receiver FRM, transmitter DME/DDE	242419	yes	
E71400	No message (ambient temperature, 0x2CA), receiver IHKA, transmitter KOMBI	-1	yes	Information
E71402	Message (data, drive train 2, 0x3F9) missing, receiver IHKA, transmitter DME/DDE	-1	yes	Information
E71405	No message (liquid crystal display brightness control, 0x328), receiver IHKA, transmitter KOMBI	-1	yes	Information
E71406	No message (power management consumer/load control, 0x3B3), receiver IHKA, transmitter DME-DDE	-1	yes	Information
E71413	Message (crankshaft torque 1, 0xA5) missing, receiver IHKA, transmitter DME/DDE	-1	yes	Information
E71415	Message (data, drive train 1, 0x3FB) missing, receiver IHKA, transmitter DME/DDE	-1	yes	Information
E71448	No message (status of MSA, 0x30B), receiver IHKA, transmitter DME/DDE	-1	yes	Information